


# FIELD INSPECTION REPORT

Date of Inspection: 27.12.2020		District: Samastipur
Division: RWD Dalsinghsarai		Length(km): 1.5
Name of Road: SH-88 to Yadav tal.		
Scheme / Programme: MAINTENANCE		OTSY
Package No:		Road Id No:
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of:		New Connectivity/ Up gradation/ Maintenance

Sl. No	Parameters to be Checked	Remarks
1	<b>Pavement</b>	
a)	Road Junction Condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	S
f)	Constraction Joint provided or not(CC Pavement)	
g)	Compaction of flank/slope & raincuts if any	R.I
2	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	
b)	Condition of Abutment & Wing walls , Slab in RCC culverts	NT
c)	Condition of railings/slab/approach for Bridge	
3	<b>Road Furniture</b>	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	R.I
4	<b>Compliance History</b>	
a)	Status of ATR's & any others	NO

Overall Rating : S.R.I

Satisfactory(S)	
Satisfactory but requires Improvement(SRI)	
Unsatisfactory(U)	

  
 27.12.2020

(Signature)

Ramesh Kumar Syl

NAME:

DESIGNATION :

J E