FIELD INSPECTION REPORT

Date of Inspection : 2:		District: Muzathapur
Division: Muzathapur East-1		Length (km): 1 /5 km
Name of the Road: Gob	mesali Sakri Smai	27 Poth Ke Ladaura chank to Ladaura Pachhigmi 7
Scheme/Programme:	MAINTENANCE M M G SY (SC)	
Package No.:		Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	
		ing to Continue the section of the s

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	H I
a)	Road Junction condition	
b)	Condition of Surfacing	
c)	Riding Quality	
d)	Road Camber	∕8/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓S/SRI/U
c)	Condition of railings/slab/approach for Bridges	→S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Bijerdon Kumor ATION: JE/RND(W) NAME:

DESIGNATION:

Kurhani'

(Signature) AE RWD (W) Kurhani