

FIELD INSPECTION REPORT

Date of Inspection: 31/12/20		District: Nalanda	
Division: H-159		Length (km): 0.4 km	
Name of the Road: Ekamper Bihar road pmguy road to Chak mustan			
Scheme/Programme: MAINTENANCE			
Scheme No.: HMGUY		Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance		under maintenance	
It is a case of: New Connectivity/Up gradation/ Maintenance		maintenance	
No.	Parameters to be checked	Remarks	
Pavement			
1)	Road Junction condition	S/U	S
2)	Condition of Surfacing	S/U	S
3)	Riding Quality	S/U	S
4)	Road Camber	S/U	S
5)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	n
6)	Construction joints provided or not (CC Pavement)	Yes/No	Y
7)	Compaction of flank slope & taluents if any	Yes/No	s
Cross Drainage			
	Condition of Road walls or Hume pipe culverts including its painting	S/SRI/U	
	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
	Condition of railings/slab approach for Bridges	S/SRI/U	
Road Furniture			
	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Y/No	
Compliance History			
Status of ATR's & any others:		No	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

E. Pradip Kumar Aye

(Signature)