## FIELD INSPECTION REPORT

Date of In	nspection: 31	112   202 10	District: Jamui	
Division :	James		District: Jamei Length (km):  .	
Name of				
Scheme/F	Programme:	Numdo Pamoly MAINTENANCE	ay of main Road to Kail	aghpun
Package	No.:		Road Id No.: 20804100	30 4
	the Project:	Ongoing/Completed	/Under Maintenance	300
Work is a	a case of:	New Connectivity/L	Jp gradation/ Maintenance	
Sl. No.		Parameters to	be checked	Remarks
1.	Pavement	d estado	Maria Company	ing stand
a)	Road Junction condition			₩8/U
b)	Condition of Surfacing			<b>√8/</b> U
c)	Riding Quality			S/U
d)	Road Camber			SAU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No N/
f)	Contraction Joints provided or not (CC Pavement)			Wes/No HIA
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drain:	igė ištaiti autorij		
a)				S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U N/
c)	Condition of railings/slab/approach for Bridges			SISRIU HA
3.	Road Furniti	ire		
a)	Whether sign stones/Pavement	ent road markings are	/cautionary Board/km & 200m provided and maintained	Yes/No
4.	Compliance	History		
a)	72-7-01-05-05-01-05-05-05-05-05-05-05-05-05-05-05-05-05-	s & any others		N6

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Pri 21/12/2020

(Signature) 4-P

NAME:

DESIGNATION: