## FIELD INSPECTION REPORT

Date of Inspection :		District: Kotihar
Division: Barson	A TABLE OF THE STATE OF THE STA	Length (km): 1.570
Name of the Road: M	MGSY Road	to Muslim Tola
Scheme/Programme:	MAINTENANCE	~ GTSNY
Package No.:		Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

Si. No.	Parameters to be checked	Remarks
1.	Payement	
a)	Road Junction condition	
b)	Condition of Surfacing	√8/U
c)	Riding Quality	
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
Ŋ	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	√\$/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts XI.A	S/SRI/U
c)	Condition of railings/slab/approach for Bridges  N•A	S/SRI/U
3.	Road Furniture	
* a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	A Park
a)	Status of ATR's & any others	NO

Overall Rating

Satisfactory (S)	-
Satisfactory but requires Improvement (SRI)	RI
Unsatisfactory (U)	-

05/03/2021 (Signature)

NAME: Mihir Kumar

DESIGNATION: J.R