FIELD INSPECTION REPORT

Date o	of Inspection : 3	30/12/2020	District: Kishongan Length (km): 0.800 Km	j
Divisi	on · /VICLa	name .	Length (km): 0.800 Km	
Name	of the Road: 3	7DP Rogel J	addu To19 Chowx To	Shopam!
Schen	ne/l'rogramme:	MAINTENANCE		The state of the s
Package No.:			Road Id No.: 81805901852	
Status of the Project: Work is a case of:		Ongoing/Completed/Under Maintenance New Connectivity/Up gradation/ Maintenance		
Sl. No.				Remarks
1.	Pavement			- Unad
a)	Road Junction condition			S/U S/C
b)	Condition of St			S/U SK
c)	Riding Quality			SAU
d)	Road Camber			SAO
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
n	Contraction Joints provided or not (CC Pavement)		Yes/No	
g)	Compaction of flank/slope & raincu		s if any	Yes/No
ž.,	Cross Drainage			
2)	Condition of head walls in Hume pipe culverts including its painting			S/SRL/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			1 . egi +
	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No J
	Compliance Hist	ory	# 15 P. 15 P	Still William
S	Status of ATR's & any others			SIT

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

(Signature)

NAME: