


# FIELD INSPECTION REPORT

Date of Inspection:		District: Samastipur	
Division: RWD Dalsinghsarai		Length(km): 2.10	
Name of Road : Samarth chand surai TO Brahman tola			
Scheme / Programme:		MAINTENANCE GTSNY	
Package No:		Road Id No:	
Status of the Project: Ongoing/Completed/Under Maintenance			
Work is a case of:		New Connectivity/ Up gradation/ Maintenance	
Sl. No	Parameters to be Checked	Remarks	
<b>1</b>	<b>Pavement</b>		
a)	Road Junction Condition	S	
b)	Condition of Surfacing	S	
c)	Riding Quality	S	
d)	Road Camber	S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	S	
f)	Constraction Joint provided or not(CC Pavement)		
g)	Compaction of flank/slope & raincuts if any	R.I	
<b>2</b>	<b>Cross Drainage</b>		
a)	Condition of head walls in Hume pipe culverts including its painting	S	
b)	Condition of Abutment & Wing walls , Slab in RCC culverts	—	
c)	Condition of railings/slab/approach for Bridge		
<b>3</b>	<b>Road Furniture</b>		
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	R.I	
<b>4</b>	<b>Compliance History</b>		
a)	Status of ATR's & any others	No	

Overall Rating : S. R. I

Satisfactory(S)	
Satisfactory but requires Improvement(SRI)	
Unsatisfactory(U)	

Ramesh Kumar Sg  
J E

  
 22.12.2020  
 (Signature)

NAME:  
DESIGNATION :