

FIELD INSPECTION REPORT

Date of Inspection :	29/12/20	District:	East Champaran
Division :	motirani	Length (km):	0.800 K.M.
Name of the Road:	House of Sansay Gini to House of Piumid Singh		
Scheme Programme:	MAINTENANCE / GTNY		
Package No.:	-		
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓/U
b)	Condition of Surfacing	✓/U
c)	Riding Quality	✓/U
d)	Road Camber	✓/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓/Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓/Yes/No
g)	Compaction of flank/slope & raincuts if any	✓/Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U - N/A -
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U - N/A -
c)	Condition of railings/slab/approach for Bridges	S/SRI/U - N/A -
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓/No
4.	Compliance History	
a)	Status of ATR's & any others	- N/A -

Overall Rating :

Satisfactory (S)	(S)
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-


29/12/20
(Signature)

NAME: maleshwar sharma

DESIGNATION: J.E.