## FIELD INSPECTION REPORT

Date of Inspection:	12.12.2020	District: Patra		
Division: Patra		Length (km): 0.475 km		
Name of the Road: Kharbbaiya to Kharbbaiya chamal Toli				
Scheme/Programme:	MAINTENANCE	MMGSY-SC		
Package No.:	Daniyawaa			
Status of the Project:	Ongoing/Completed/Under Maintenance			
Work is a case of:		p gradation/ Maintenance		

by Branch Mantenance	
Parameters to be checked	Remarks
Pavement	ANIA TARA
Road Junction condition	
Condition of Surfacing	√8′/U
Riding Quality	_8/U
Road Camber	√S/U
Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	√Yes/No
Contraction Joints provided or not (CC Pavement)	√Yes/No
Compaction of flank/slope & raincuts if any	X'es/No
Cross Drainage	
Condition of head walls in Hume pipe culverts including its painting	√8/SRI/U
Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U >
Condition of railings/slab/approach for Bridges	S/SRI/U
Road Furniture	
Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
Compliance History	
Status of ATR's & any others	No
	Parameters to be checked  Pavement  Road Junction condition  Condition of Surfacing  Riding Quality  Road Camber  Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.  Contraction Joints provided or not (CC Pavement)  Compaction of flank/slope & raincuts if any  Cross Drainage  Condition of head walls in Hume pipe culverts including its painting  Condition of Abutment & Wing walls, Slab in RCC culverts  Condition of railings/slab/approach for Bridges  Road Furniture  Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained  Compliance History

Overall Rating :

Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Hi manshu Ray DESIGNATION: AE