FIELD INSPECTION REPORT

			· · · · · · · · · · · · · · · · · · ·		
Date of Inspection: 22-12-2020 District: Patra					
Division: Patra Length (km): 0.575 Km					
Name of the Road: To 7 to Mustafapur Hariyan Toli					
Name of the Road: To 7 to Mustafapur Hariyan Toli Scheme/Programme: MAINTENANCE MM654-SC					
Package No.: Daniyawan Road Id No.:					
-6-70/Z (05)			ompleted/Under Maintenance		
Work is a case of:		New Connectivity/Up gradation/ Maintenance		5	
Sl. No.		Parameters to	be checked	Remarks	
1.	Pavement			1994	
á)	Road Junction condition			S/U	
b)	Condition of Surfacing			✓S/U	
c)	Riding Quality			√S/U	
d)	Road Camber			✓S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	N/0
f)	Contraction Joints provided or not (CC Pavement)			Yes/No }	Just
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			8/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U)	, ,
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	NA
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
4,	Compliance History			The state of the s	
a)	Status of ATR's & any others			NO	
Overall Rating : Restoration of Potholes is in progress					
Satisfactory (S)					
			equires Improvement (SRI)	SRI	
		Unsatisfactory (U)			

(Signature)

NAME: Himanshu Roj DESIGNATION: 4E