FIELD INSPECTION REPORT

Date of Inspection: 28.12.2020 District: Palita				
Division:	Patra	Length (km): 3.018		
Name of the Road: PMGsy Gyaspur Mahaji to Yadan Tola				
Scheme/Programme: MAINTENANCE MMG'SY SC				
Package No.: Bakhtyerpu Road Id No.:				
Status of the Project: Ongoing/Completed/Under Maintenance				
Work is a case of: New Connectivity/Up gradation/ Maintenance				
Sl. No.	Parameters to	be checked	Remarks	
1. Paver	nent	The state of the s		
a) Road	Road Junction condition			
b) Condi	Condition of Surfacing			
c) Riding	Riding Quality			
d) Road	Road Camber			
	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			
f) Contra	Contraction Joints provided or not (CC Pavement)			
g) Comp	Compaction of flank/slope & raincuts if any			
2. Cross	2. Cross Drainage			
a) Condi	tion of head walls in Hume pip	s/sri/U		
b) Condi	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U >	
c) Condi	Condition of railings/slab/approach for Bridges		S/SRI/U J	
3. Road	Road Furniture			
a) stones	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
4. Comp	liance History			
a) Status	of ATR's & any others			

Overall Rating

Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Hi maushu Roy DESIGNATION: 4E