

FIELD INSPECTION REPORT

Date of Inspection : 05/01/2024 District : Aizawl
 Division : R.W.D. & V - Aizawl Length (km) : 1.2
 Name of the Road : Poribing, Maly Road to Champun District
 Scheme/Programme : MAIN NANCE
 Package No. : G.T. SM Road Id No. :
 Status of the Project : Ongoing/Completed/Under Maintenance
 Work is a case of : New/Connectivity/Up gradation/ Maintenance

Sl. No.	Particulars to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ SRI
b)	Condition of Surfacing	✓ SRI
c)	Riding Quality	✓ SRI
d)	Road Camber	✓ SRI
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ SRI/No
f)	Contraction joints provided or not (CC Pavement)	✓ SRI/No
g)	Compaction of flank/slope & raincuts if any	✓ SRI/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ SRI/No
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ SRI/No
c)	Condition of railings/slab/approach for Bridges	✓ SRI/No
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones Pavement road markings are provided and maintained	✓ SRI/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	✓
Satisfactory but requires improvement (SRI)	
Unsatisfactory (U)	

NAME : Dring Nath Rng

Dring Nath Rng
 05/01/2024
 (Signature)