## FIELD INSPECTION REPORT

	Name of the Road: protogram school Koitykg to Sultangang H				
Package No.: Road Id No.:					
-	the Project:	Ongoing/Completed/Under Maintenance Mo	portagon		
Work is	a case of:	New Connectivity/Up gradation/ Maintenance	1		
SI. No.		Parameters to be checked	Remarks		
1.	Pavement				
a)	Road Junction condition		S/U		
b)	Condition of Surfacing		S/U		
c)	Riding Quality				
d)	Road Camber		S/U		
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				
f)	Contraction Joints provided or not (CC Pavement)		Yes/No		
g)	Compaction of flank/slope & raincuts if any		Yes/No		
2.	Cross Drainage				
a)	Condition of	S/SRI/U			
b)	Condition of Abutment & Wing walls, Slab in RCC culverts				
c)	Condition of railings/slab/approach for Bridges S/S		S/SRI/U		
3.	Road Furniture				
a)	Whether signstones/Pavern	Yes/No			
4.	Compliance History				
a)	Status of ATI	R's & any others			

Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	_
Unsatisfactory (U)	

(Signature)

NAME: M. P. RAFFIQUE ALAN

DESIGNATION: