FIELD INSPECTION REPORT

Date of Inspection: 05.01.2021 Length (km): 0.825

Distrcit: SARAN

Division: SONPUR

Name of the Road: Harpur Ke Karunalal Ghar Hote Huye to Pokhrapur Tak

Scheme/Programme: MAINTENANCE

Road ID No: Package No:

Status of The Project: MAINTENANCE

SI.No	s a case of : Maintenance Parameters to be checked	Remarks
1	Pavement	
	Road Junction Condition	5
a)		S
b)	Condition of Surfacing	5
c)	Riding Quality	S
d) e)	Road Camber Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	s
0	Contraction Joints provided or not (CC Pavement)	5
g)	Compaction of Flank/slope & raincuts if any	5
2	Cross Drainage	
a)	Condition of head walls in Hume pipe Culverts including its painting	S
b)	Condition of Abutment & Wing Walls, Slab in RCC Culverts	S
c)	Condition of railings/slab/approach for Bridges	S
3	Raod Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	S
4	Compliance History	
a)	Status of ATR's any others	NO

Overall Rating:

CACLOLI MOTING :	
Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME:- RAJEEV RANJAN KUMAR DESIGNATION: JUNIOR ENGINEER