## FIELD INSPECTION REPORT

Date of Inspection: 31-12-2020 District:				PATHA	
Name of the Pool			Length (km):	0.30	
Control of the Contro	Programme:	Devchand Tul	a to Punit Tola		
Package	ragialinie;	MAINTENANCE			1
	f the Project:	Ongoin-/C	Road Id No.:	A SEAS	
	a case of:		ed/Under Maintenance /Up gradation/ Maintenance		
Sl. No.	Parameters to be checked				Remarks
1.	Pavement				
a)	Road Junction condition				S S/U
b)	Condition of Surfacing				S S/U
c)	Riding Quality				S S/U
d)	Road Camber				S S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Payement.				
f)	Contraction Joints provided or not (CC Pavement)				_ Yes/No
g)	Compaction of flank/slope & raincuts if any				- Yes/No
2.	Cross Drain:	age			Service 2
a)	Condition of head walls in Hume pipe culverts including its painting				HA S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			MA S/SRI/U	
c)	Condition of	railings/slab/approa	ch for Bridges		HA S/SRI/U
3.	Road Furnit	ure			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				Yes/No
4.	Compliance History				
a)	Status of ATR's & any others				
Overall	Dating .				
Overall	Raung	Satisfactory (S	s) ut requires Improvement (		S

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

DINGSH CHOWHARY

NAME: