

FIELD INSPECTION REPORT

Date of Inspection: 06.01.2021 District: Patna
 Division: Danapur Length (km): 2.00 km
 Name of the Road: Sadikpur Bagicha Village to Sirhindpur ITI Bridge
 Scheme Programme: MAINTENANCE
 Package No.:
 Status of the Project: Ongoing/Completed/Under Maintenance under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/CRIT
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO ATR

Overall Rating :

Satisfactory (S)	S ✓
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Georg
6/1/2021
P.E

DESIGNATION:
(SC Singh)

Bhag
6/1/2021
JE
(BX Singh)

S. Kumar
6.1.2021
A.E. Maner
(Somnath Ram)

(Signature)