

FIELD INSPECTION REPORT

Date of Inspection : 5.1.21 District: Aurangabad
 Division : Aurangabad Length (km): 2.13 km
 Name of the Road: 1092 - T01 Red Jiva Bgha Road Sargawan
 Scheme/Programme: MAINTENANCE
 Package No.: BRD2R-662 Road Id No.:
 Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S S/I
b)	Condition of Surfacing	S S/I
c)	Riding Quality	S S/I
d)	Road Camber	S S/I
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI
c)	Condition of railings/slab/approach for Bridges	S/SRI
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km. & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History Brgues found, Raincuts in shoulder,	
a)	Status of ATR's & any others No Maintenance Board found	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	


 5.1.21
 (Signature)

NAME: