

FIELD INSPECTION REPORT

Date of Inspection : 4.01.21	District: Anuragabad
Division : Anuragabad	Length (km): 1.85 Km
Name of the Road: L.S. to Mahuramam.	
Scheme/Programme: MAINTENANCE	
Package No.: DR-D2R-704	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S S/U
b)	Condition of Surfacing	S S/U
c)	Riding Quality	S S/U
d)	Road Camber	S S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	yes Yes/No
f)	Contraction Joints provided or not (CC Pavement)	yes Yes/No
g)	Compaction of flank/slope & raincuts if any	yes Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its par	SRI S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	- S/SRI/U
c)	Condition of railings/slab/approach for Bridges	- S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km. & stones/Pavement road markings are provided and maintained	200m No Yes/No
4.	Compliance History	Repairment in flank. Buelies done
a)	Status of ATR's & any others	Scale in 150m, Maintenance Board not found, Road furniture not found.

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

[Signature]
4.1.21
(Signature)

NAME: Babbar
A.E