ドアワント FIELD INSPECTION REPORT

| Date of Inspection : | | District: Rohf | |
|------------------------|--|---------------------|--|
| Division: | | Length (km): 3-970 | |
| Name of the Road: /d | 21941312 4 | चामप्र न्यार पण | |
| Scheme/Programme: | MAINTENANCE | PMULY | |
| Package No.: MR | 8R-192 | Road Id No.: | |
| Status of the Project: | Ongoing/Complete | d/Under Maintenance | |
| Work is a case of | New Connectivity/Up gradation/ Maintenance | | |

| SI. No. | Parameters to be checked | Remarks | |
|---------|--|---------|--|
| 1. | Pavement | / | |
| a) | Road Junction condition | s/u | |
| b) | Condition of Surfacing | Ś/U | |
| c) | Riding Quality | S/U | |
| d) | Road Camber | \$/U | |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | Yes/No | |
| f) | Contraction Joints provided or not (CC Pavement) | Yes/No | |
| g) | Compaction of flank/slope & raincuts if any | Yes/No | |
| 2 | Cross Drainage | | |
| a) | Condition of head walls in Hume pipe culverts including its painting | S/SRI/U | |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | S/SRI/U | |
| c) | Condition of railings/slab/approach for Bridges | | |
| 3. | Road Furniture | | |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | | |
| 4. | Compliance History | | |
| a) | Status of ATR's & any others | | |

Overall Rating

| Satisfactory (S) | 5 |
|---|---|
| Satisfactory but requires Improvement (SRI) | |
| Unsatisfactory (U) | |

05.01.21

(Signature)

NAME:

DESIGNATION: