

FIELD INSPECTION REPORT

Date of Inspection : 05/01/2021		District: vaishali
Division : mahar		Length (km): 0.290 km
Name of the Road: NH-103		UM बिहारी क पिके ए डी डी - पदम हिल
Scheme/Programme: MAINTENANCE		UTSAY
Package No.:		Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance		✓
Work is a case of:		New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U S
b)	Condition of Surfacing	S/U S
c)	Riding Quality	S/U S
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes/No Yes
g)	Compaction of flank/slope & raincuts if any	Yes/No Yes
2.	Cross-Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No Yes
4.	Compliance History	
a)	Status of ATR's & any others	ATD

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	


(Signature)

NAME: Rinki Kumari

DESIGNATION: J.E