

FIELD INSPECTION REPORT

Date of Inspection : 05-01-2021		District: Gaya	
Division : Gaya		Length (km): 0.503	
Name of the Road: Gaya Shergate Road To Gularichak			
Scheme/Programme: MAINTENANCE			
Package No.:		Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance			
Work is a case of: New Connectivity/Up gradation/ Maintenance			
SL No.	Parameters to be checked	Remarks	
1. Pavement			
a)	Road Junction condition	✓ S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	✓ S/U	
d)	Road Camber	✓ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2. Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SR/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U N/A	
c)	Condition of railings/slab/approach for Bridges	S/SR/U N/A	
3. Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No	
4. Compliance Highway			
a)	Status of ATR's & any others	N/A	

Overall Rating :

Satisfactory (S)	✓ S/
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Chandan Chatterjee Kumar

DESIGNATION: JE

(Signature)
5.1.2021

(Signature)