

FIELD INSPECTION REPORT

Date of Inspection : 04/01/21		District: Vaishali	
Division : mahar		Length (km): 0.46 km	
Name of the Road: R.E.O. G.S.N. 21 1st 1/2 mile to 2nd 1/2 mile		21 2nd 1/2 mile to 3rd 1/2 mile	
Scheme/Programme: MAINTENANCE		mmmsy	
Package No.:		Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance		✓	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Concrete Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Signage	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	General Remarks	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


(Signature)

NAME: RINKU KUMARI

DESIGNATION: J.E.