

FIELD INSPECTION REPORT

Date of Inspection :	District: <u>Aurangabad</u>	
Division: <u>Daholkarpet</u>	Length (km):	
Name of the Road: <u>BKSI Bishka to B-19K/ Gankoriy</u>		
Scheme Programmes: <u>MAINTENANCE</u>	<u>Angur HH&SY (SC)</u>	
Package No.:	Road Id No.:	
Status of the Projects:	Ongoing/Completed/Under Maintenance <u>Ongoing</u>	
Work is a case of:	New Connectivity/Up gradation/ Maintenance <u>New work</u>	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Remarks: - Work is in under construction stage - ongoing.

(Signature)

NAME:

DESIGNATION: