

FIELD INSPECTION REPORT

Date of Inspection :		District: <u>Arrang, LW</u>
Division: <u>Dauk 1498</u>	Length (km): <u>2-965 km</u>	
Name of the Road: <u>Bhe 19 Bigha Ry to Dorniyon</u>		
Scheme Programme:	MAINTENANCE	
Package No.:	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance <u>on going</u>	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U 5
b)	Condition of Surfacing	S/U 5
c)	Riding Quality	S/U 5
d)	Road Camber	S/U 5
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No <u>No</u>
f)	Contraction Joints provided or not (CC Pavement)	Yes/No <u>Yes</u>
g)	Compaction of flank/slope & raincuts if any	Yes/No <u>Yes</u>
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U 5
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U 5
c)	Condition of railings/slab/approach for Bridges	S/SRI/U <u>NA</u>
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No <u>Yes</u>
4.	Compliance History	
a)	Status of ATR's & any others	<u>No.</u>

Overall Rating :

Satisfactory (S)	<u>5</u>
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Remarks: Work completed on
21/11/2020

Shy am
4/10/2021
(Signature) ATC

NAME:

DESIGNATION: