## FIELD INSPECTION REPORT

Date of I				
Division	: Pa	6.12-2020 tra	Length (km): 0.915 Kg	20
Name of	the Road: F	MGSY Road (	District: Patria Length (km): 0.915 Kr Champapur to Yado	w Toli
Scheme/	Programme:	MAINTENANCE	NABARD	
Package		Bakhtiyarpur	Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance		
A TO A A STATE OF THE PARTY OF	a case of:		p gradation/ Maintenance	
Sl. No.		Parameters to	be <b>che</b> cked	Remarks
1:	Pavement.			
a)	Road Junction condition			_S/U
b)	Condition of Surfacing			√S/U
c)	Riding Quality			√S/U
d)	Road Camber			√S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Xes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2:	Cross Draina	ge		
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U )
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U \$
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furnitu	re		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4,	Compliance B	listory		
a)	Status of ATD	's & any others	A SALES AND STREET	NO

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Hi manshy Roj DESIGNATION: 15