FIELD INSPECTION REPORT

Date of	Inspection :	5[1 21	District: Patner	
Divisio	n: Me	naur hi	Length (km): 2.358 K	
Name o	of the Road: "I	ou latour Pan	PMASY Pata to Ro	mgadh
	/Programme:		MMG14CGood anda	my (E) WL
Packag			Road Id No.:	Progress
	of the Project: a case of:	Ongoing/Completed/University/Univ	gradation/ Maintenance	
SI. No.	The second second		THE RESERVE OF THE PARTY OF THE	Remarks
1.	Pavement	Parameters to be checked Remai		
-		and the	# C35-D12-003-303	0.01
n)	Road Junction		S/U	
b)	Condition of Surfacing			S/U
(c)	Riding Quality			S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
1)	Contraction Jo	ontraction Joints provided or not (CC Pavement)		
g) .	Compaction of flank/slope & raincuts if any			Yes/No
2,	Cross Draina	ge		164
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of ra	ndition of railings/slab/approach for Bridges		
3.	Road Furnitu	re	1 1 1 3 1 1 - L	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4,	Compliance History			
a)	Status of ATR's & any others			HOBTA
verall R	tating :			
1	The Life	Satisfactory (S)		5
		Satisfactory but rec	quires Improvement (SRI)	-

Satisfactory (S)	S	
Satisfactory but requires Improvement (SRI)		
Unsatisfactory (U)	-	

5/1/21 (Signature)

phle

Pushkar Prasad Ars H. Cersinen NAME: