FIELD INSPECTION REPORT

Date of	Inspection:	25.01.21	District: Roh 1-3		
Division: Jeser-n-L			Length (km): 0540km		
		विकाजाट थां	MA LIDE PWD X	な	
Other Designation of the last	/Programme:	MAINTENANCE	mmosy		
Package	No.:		Road Id No.:		
Status o	f the Project:		I/Under Maintenance		
Work is	a case of:	New Connectivity/L	Jp gradation/ Maintenance		
SI. No.	Parameters to be checked		Remarks		
1.	Pavement				
a)	Road Junction condition			S/U	
b)	Road Junction condition Condition of Surfacing			S/U	
c)	Riding Quality Road Camber			S/U	
d)	Road Camber NO			S/U	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2	Cross Drains	.			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Rurniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
	Compilance Elistory				
8)	Status of ATR's & any others			M	

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	******

2005.01.21

(Signature)

NAME:

DESIGNATION: