## FIELD INSPECTION REPORT

rate of Inspection : 5-1, 21			District: KAIMUR Length (km): 1.18 Km.		
heme/P	rogramme: MAI	NTENANCE	mmasy (se)		
ckage !	Vo.:	1 1/2	Road Id No.:	· ·	1
	the Project: Ong	oing/Complete	d/Under Maintenance Up gradation/ Mainten	ance	-
	case of: Vew		and the second s	- 1	Remarks
L No.		Parameters to	) he checked		
1.	Pavement	111	ALLEGATION OF THE PARTY OF THE	State of Market	VS/U
a)	Road Junction condition				
b)	Condition of Surfacing				<i>S</i> (U
(2	Riding Quality				VS/U
d)	Road Camber				L870
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				Yes/No
f)	Contraction Joints provided or not (CC Pavement)				Yes/No
g)	Compaction of flank/slope & raincuts if any				Yes/No
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting				S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts				S/SRI/U
c)	Condition of railings/slab/approach for Bridges				S/SRI/U
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				Yes/No
4.	Compliance History				
a)	Status of ATR's & any others			No	
Overa	il Rating :	Satisfactory (S	8)		(8)
		The second secon	ut requires Improver	nent (SRI)	-
	,	Unsatisfactor	y (U)		

(Signature) 5/1/21 5-Rev

NAME: Satzundry Rosed Lad