

FIELD INSPECTION REPORT


Date of Inspection : 5-1-21		District: KAZMUR	
Division :		Length (km): 0.40 km	
Name of the Road: Larma Jemuni to Larma Hanjortola			
Scheme/Programme: MAINTENANCE		mmgsy (se)	
Package No.:		Road Id No.:	
Status of the Project: <input checked="" type="checkbox"/> Ongoing/Completed/Under Maintenance			
Work is a case of: <input checked="" type="checkbox"/> New Connectivity/Up gradation/ Maintenance			

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m ✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	xb

Overall Rating :

Satisfactory (S)	(S)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Satyendra Basal Lal


 (Signature) 5/1/21
 S.R.