

FIELD INSPECTION REPORT

Date of Inspection :		District: <u>Aurangabad</u>
Division: <u>Dhuley Key 97</u>		Length (km): <u>2.845 km</u>
Name of the Road: <u>Bibi p48 to B9/Want Bish</u>		
Scheme Programme: <u>MAINTENANCE</u>		<u>MMSSY (SC)</u>
Package No.:		Road Id No.:
Status of the Project:		Ongoing/Completed/Under Maintenance <u>Ongoing</u>
Work is a case of:		New Connectivity/Up gradation/ Maintenance
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

2

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

REMARKS - Work not started.

Stage - engine

(Signature)

NAME:

DESIGNATION: