

# FIELD INSPECTION REPORT

|                        |                                            |              |           |
|------------------------|--------------------------------------------|--------------|-----------|
| Date of Inspection :   | 01/01/2021                                 | District:    | Kaimur    |
| Division :             | Mohaniya                                   | Length (km): | 0.900 KM. |
| Name of the Road:      | Canal Road to Panchgai Bind Tola.          |              |           |
| Scheme/Programme:      | MAINTENANCE                                |              |           |
| Package No.:           |                                            | Road Id No.: |           |
| Status of the Project: | Ongoing/Completed/Under Maintenance        |              |           |
| Work is a case of:     | New Connectivity/Up gradation/ Maintenance |              |           |

| Sl. No. | Parameters to be checked                                                                                             | Remarks   |
|---------|----------------------------------------------------------------------------------------------------------------------|-----------|
| 1.      | Pavement                                                                                                             |           |
| a)      | Road Junction condition                                                                                              | - S/U     |
| b)      | Condition of Surfacing                                                                                               | ✓ S/U     |
| c)      | Riding Quality                                                                                                       | - S/U     |
| d)      | Road Camber                                                                                                          | ✓ S/U     |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | Yes/No    |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | Yes/No    |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | Yes/No    |
| 2.      | Cross Drainage                                                                                                       |           |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | ✓ S/SRI/U |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U   |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U   |
| 3.      | Road Furniture                                                                                                       |           |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | ✓ Yes/No  |
| 4.      | Compliance History                                                                                                   |           |
| a)      | Status of ATR's & any others                                                                                         | NO        |

Overall Rating :

Satisfactory (S)  
Satisfactory but requires Improvement (SRI)  
Unsatisfactory (U)

work going on progress.

01/01/2021  
(Signature)

NAME: Santosh Kumar Tiwary