

FIELD INSPECTION REPORT

Date of Inspection :	5/1/21	District:	Patna
Division :	Masauri	Length (km):	11.570
Name of the Road:	709 - Hadwar to onyara		
Scheme/Programme:	MAINTENANCE PMGSY II	/ ongoing surface work	
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S S/U
b)	Condition of Surfacing	S S/U
c)	Riding Quality	S S/U
d)	Road Camber	S S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	— Yes/No
f)	Contraction Joints provided or not (CC Pavement)	— Yes/No
g)	Compaction of flank/slope & raincuts if any	— Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	— S/SRI/U
c)	Condition of railings/slab/approach for Bridges	— S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m Yes Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No ATR

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME:

Puskar Prasad
Asst H. Engineer

Puskar Prasad
5/1/21
(Signature)