

FIELD INSPECTION REPORT

mmasy (Gen) (i)

Date of Inspection : 18/12/20	District: Patna.
Division : Patna.	Length (km): 1.280
Name of the Road: Pipra Main Road to Main Road Shiv mandir b/w.	
Scheme/Programme: MAINTENANCE	mmasy (Gen) Shahpur and Bampur
Package No.:	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	S
a)	Road Junction condition	S
b)	Condition of Surfacing	U
c)	Riding Quality	U
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
f)	Contraction Joints provided or not (CC Pavement)	S
g)	Compaction of flank/slope & raincuts if any	S
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A
c)	Condition of railings/slab/approach for Bridges	Yes.
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

Note: - Badly damaged in flood 2019 & emergent work has been done in 1km. Subriya
18/12/20
(Signature)

NAME: Subriya Rani
DESIGNATION: Assistant Engineer
RWD (w) Subdivision.
Sampatchak Patna.