mongs in Gen)

FIELD INSPECTION REPORT

Date of I	nspection:	21.12.20	District: Palma,		
Division					
	the Road: To	1 (Patria Gaya	Patty to Jaiwar Patt	near Power or	01
	Programme:	MAINTENANCE		near Power or	tolc
Package No.:			Road Id No.:		7 101
Status of the Project: Ongoing/Completed/Unc			ed/Under Maintenance	-	
Work is a case of: New Connectivity/Up gradation/ Maintenance					
S1: No.	E-PARTIE -	Parameters (o be checked	Remarks	
A A	Pavement				
a)	Road Junction condition			S	
b)	Condition of Surfacing			2	
c)	Riding Quality	Y			
d)	Road Camber			2	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			S	
f)	Contraction Joints provided or not (CC Pavement)			S	
g)	Compaction o	f flank/slope & rain			
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its point.				
b)	Condition of 7				
c)	Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges			NIA	
訓3毫	Road Furniture			-AIN	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
製化製	Compliance I				
a)		's & any others	i de la constant de la sensona	是被某些	

Overall Rating

0.0	
Satisfactory (S)	
Satisfactory but requires Improvement (Control	
Unsatisfactory (U)	
	11

121/12/20

Supriya.

21/12/20
(Signature)

NAME: SUPRIM RONI

DESIGNATION: A.E. Samptchak