FIELD INSPECTION REPORT

Date of L	espection: 22 - 12 - 22 22	District: Palue	
Date of Inspection: 22.12.2020 Division: Patre		Length (km): / · 300 Km	
	the Road: PMGSY Kharbhay		
		MMGSY-SC	
Scheme/Programme: MAINTENANCE MMC, SY-SC Package No.: Danisawan Road Id No.:			
	the Project: Ongoing/Complete	d/Under Maintenance	
Work is	case of: New Connectivity/	New Connectivity/Up gradation/ Maintenance	
Sl. No.	The state of the s	be checked	Remarks
1.	Pavement		
a)	Road Junction condition		S/U
b)	Condition of Surfacing		√S/U
c)	Riding Quality		✓S/U
d)	Road Camber		✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Xes/No
g)	Compaction of flank/slope & raincuts if any		Xes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U)
c)	Condition of railings/slab/approach for Bridges		S/SRI/U J
3.	Road Furniture		
a)	Whether sign boards/informatory stones/Pavement road markings are	c/cautionary Board/km & 200m c provided and maintained	Yes/No
			ing to a sixty and

Overall Rating

a)

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	Ŷ
Unsatisfactory (U)	
eist.	

NAME: Himaushu Roj DESIGNATION: ALE

Status of ATR's & any others