

mmgsy(sc)

FIELD INSPECTION REPORT

Date of Inspection :	21.12.20.	District:	Patna,
Division :	Patna,	Length (km):	1.150 km
Name of the Road:	Mithanchak main Road To Mithanchak Mahila dalit hdq		
Scheme/Programme:	MAINTENANCE	mmgsy(sc)	
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	S
a)	Road Junction condition	S
b)	Condition of Surfacing	U
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
f)	Contraction Joints provided or not (CC Pavement)	S
g)	Compaction of flank/slope & raincuts if any	S
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A
c)	Condition of railings/slab/approach for Bridges	N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	U
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	U

No Te: - Road length 1.00 km is submerged in flood water during flood 2019 & damaged.

NAME: Supriya Rani

DESIGNATION: AE, Sampatchak
Patna. Div.

Supriya
21/12/20
(Signature), A.E