



# FIELD INSPECTION REPORT

<b>Date of Inspection :</b>		25/12/2020		<b>District :</b>		Munger	
<b>Division :</b>		Kharagpur-Tarapur		<b>Length (Km) :</b>		0.786 Km	
<b>Name of the Road :</b>		L063-P.W.D.ROAD KHARAGPUR JAMUI T-01 MOHANPUR RAMBIHARI PUR (VR63)					
<b>Scheme/Programme :</b>		MAINTENANCE					
<b>Package No. :</b>		BR22R117		<b>Road Id No. :</b>			
<b>Status of the Project :</b>		Ongoing/Completed/Under Maintenance				Under Maintenance	
<b>Work is a case of :</b>		New Connectivity/Up gradation/Maintenance				Maintenance	
<b>Sl. No.</b>	<b>Parameters to be checked</b>					<b>Remarks</b>	
<b>1</b>	<b>Pavement</b>						
a)	Road Junction condition					S/U	S
b)	Condition of Surfacing					S/U	S
c)	Riding Quality					S/U	S
d)	Road Camber					S/U	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.					Yes/No	Y
f)	Contraction Joints provided or not (CC Pavement)					Yes/No	Y
g)	Compaction of flank/slope & raincuts if any					Yes/No	No
<b>2</b>	<b>Cross Drainage</b>						
a)	Condition of head walls in Hume pipe culverts including its painting					S/SRI/U	SRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts					S/SRI/U	NA
c)	Condition of railings/slab/approach for Bridges					S/SRI/U	NA
<b>3</b>	<b>Road Furniture</b>						
a)	Whether sign boards/informatory/cautionary board/Km & 200m stones/Pavement road markings are provided and maintained					Yes/No	Y
<b>4</b>	<b>Compliance History</b>						
a)	Status of ATR's & any others					No	

Overall Rating :

<b>Satisfactory (S)</b>	
<b>Satisfactory but requires Improvement (SRI)</b>	SRI
<b>Unsatisfactory (U)</b>	

  
 J.E.  
 25/12/2020

  
 A.E.  
 25/12/2020