## FIELD INSPECTION REPORT

Date of	Inspection :	69	District: DATE			
				H		
Name o	f the Road: P	DASAURHI EKA	engin (km): O.	120 10	M. DANIA	WAS THUS
Scheme	/Programme:	MAINTENANCE	mmusy (S	ILA ·	N BNAIN	bed hou
Package	e No.:		load Id No.:	-		
	of the Project:	Ongoing/Completed/Ur	nder Maintenance	1		
Work is	s a case of:	New Connectivity/Up g	gradation/ Maintenance	e		
SI. No.		Parameters to be	checked		Remarks	
1.	Pavement					
a)	Road Junction condition				-S/U	
b)	Condition of Surfacing				SAL	
e)	Riding Quality				50	
d)	Road Camber				SI	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				Yerko	
f)	Contraction Joints provided or not (CC Pavement)			Vesto		
g)	Compaction of flank/slope & raincuts if any			Yes/No		
2.	Cross Drainage					
a)	Condition of head walls in Hume pipe culverts including its painting				S/SRDU	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts				S/SRI/U	MA
c)	Condition of railings/slab/approach for Bridges				S/SRE/U	
3.	Road Furniture					
a)	Whether sign stones/Pavemen	boards/informatory/cauti nt road markings are prov	ionary Board/km & ided and maintained	200m	Yorko	
4.	Compliance History					
a)	Status of ATR'	s & any others				

Overall Rating

Satisfactory (S)	1,1
Satisfactory but requires Improvement (SRI)	2
Unsatisfactory (U)	

(Signature)

NAME: TES PRPTAP