

FIELD INSPECTION REPORT

Date of Inspection : 06/01/2021	District: East Champaran
Division : WORKS Divn DHAKA	Length (km): 1.435km
Name of the Road: Madhubani Khadi Bhandar to Madhubani Harijani to La.	
Scheme/Programme: MAINTENANCE Mukhy & Mantri Gram Samiksha yojana	
Package No.:	Road Id No.: 31708601339
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U } Painting required
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.	S/SRI/U }
c)	Condition of railings/slab/approach for Bridges	S/SRI/U }
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No } Painting Required
4.	Compliance History	
a)	Status of ATR's & any others	N.A

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—

NAME: SANJAY KUMAR

DESIGNATION: J.E

06/01/2021
J.E / Chiranga

06/01/21
(Signature)