

Inspection Report for Flood Damage Work

Date:

1. Name of PIUs - Gyan Vibhakar (EE RWD East-1 muzaffarpur)
2. Name of Block/Road - mirapur / Ghosant RGO Road to soda purbitala

A. For Road

1. Damage Location/Chainage : 0.250 km, 0.300 km, 0.450 km, 0.950 km, 1.0 km,
2. Damage Length : 0.152 km 1.2 km, 1.45 km
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works : Brick bats & local sand
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length : 0.152 km

B. For Bridge

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works :
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length :

Signature of JE/AE/EE

[Signature]
18-11-20
Signature

(Name of Inspector)

EE

RWD WORK Division
muzaffarpur East-1

GENERAL ABSTRACT

Name of Road Ghosaut REO Road to Sodha Purbi Tola

District Muzaffarpur

Block Minapur

Division Muzaffarpur East-2

Length of Road (in Km) 1.500 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	15.424
2	Sand Filling	0.234
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	15.658
TOTAL COST OF PROJECT IN LACS =		15.658

Say 13.64 lac

[Signature]
11/11/2020

JE
RWD

[Signature]
11/11/20

AE
RWD

[Signature]
11/11
EE
RWD

Technically approved for RS 13.64 lac
(Rupees Thirteen lac sixty four thousand only)

[Signature]
12.12.20
SE

RWD work circle
muzaffarpur