

Inspection Report for Flood Damage Work

Date:

1. Name of PIUs - Gyan vibhakar
2. Name of Block/Road - Minapur / Nalnama prusy to unhasant
pachimi Tola.


A. For Road

1. Damage Location/Chainage : 0.02km, 0.1km, 0.2km, 0.32km, 0.41km, 0.52km, 0.61km
2. Damage Length : 0.115km
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works : BRICK BEDS
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length : 0.115km

B. For Bridge

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works :
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length :

Signature of JE/AE/EE


Signature

(Name of Inspector)

• EE


RWD WORK DIVISION
MUZAFFARPUR EAST-1

GENERAL ABSTRACT

Name of Road Naknama PMGSY to Ghosaut Pachimi Tola
District Muzaffarpur
Block Minapur
Division Muzaffarpur East-2
Length of Road (in Km) 2.000 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
		1.193
1	Jhama metal	0.000
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	1.193
	GRAND SUB TOTAL	1.193
TOTAL COST OF PROJECT IN LACS =		1.193

Say 1-19 Lakh


13/12/20


JE
RWD


13/12/20

AE
RWD


EE
RWD

Technically approved for RS 1.19 lakh (Rupees one lakh nineteen thousand only)


SE

RWD WORK CIRCLE
MUZAFFARPUR