

Inspection Report for Flood Damage Work

Date

- 1 Name of PIUs- *Gyan vibhakar*
2 Name of Block/Road- *Kata/Besat musy path me Ram Bhad Singh ice ghos to meh gaur path tak.*

A ☒ For Road

- 1 Damage Location/Chainage *0.100km, 0.150km, 0.200km, 0.320km*
2 Damage Length *0.050km*
3 Nature of Damage
4 Details of Restoration Works-
i Material being used in Restoration Works- *Brick bats & local sand*
ii Equipments/Tools being used in Restoration Works-
iii Procedure Taken up in Restoration Works-
iv Restored Length - *0.050km*

B. ☐ For Bridge

- 1 Damage Location/Chainage
2 Damage Length
3 Nature of Damage
4 Details of Restoration Works-
i Material being used in Restoration Works-
ii Equipments/Tools being used in Restoration Works-
iii Procedure Taken up in Restoration Works-
iv Restored Length

Signature of JE/ AE/ EE

[Signature]
12.12.20
Signature
(Name of Inspector)

EE
RWD zone division
muzaffarpur East - 1

GENERAL ABSTRACT

Name of Road	Berai MMGSY Path me Ram Binod Singh ke Ghar to Meharoli Path Tak		
District	Muzaffarpur		
Block	Katra		
Division	Muzaffarpur East-2		
Length of Road (in Km)	2.000 Km		

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	4.675
2	Sand Filling	0.079
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	4.754
TOTAL COST OF PROJECT IN LACS =		4.754

say 4.75 lve

~~Ramch~~
25/11/2020

JE
RWD

MJ - 25.7.2020

AE
RWD

~~Qm 7/1~~

EE
RWD

Technically approved for Rs 4.75 lac
(Rupees Four lac seventy five thousand only)

1/11/2012
SE

RWD WORK circle
muzaffarpur