

Inspection Report for Flood Damage Work

Date:

1. Name of PIUs -

Gyan vibhakar

2. Name of Block/Road -

Bhatuliya Deri Mandir to gangi chakra.

A. For Road

1. Damage Location/Chainage : 0.800 km to 0.856 km

2. Damage Length : 56 m (0.056 km)

3. Nature of Damage :

4. Details of Restoration Works :

i. Material being used in Restoration works : brick bats & local sand

ii. Equipments/Tools being used in Restoration works:

iii. Procedure taken up in Restoration works :

iv. Restored Length : 56 m (0.056 km)

B. For Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration Works :

i. Material being used in Restoration works :

ii. Equipments/Tools being used in Restoration works:

iii. Procedure taken up in Restoration works :

iv. Restored Length :

Signature of JE/AE/EE


Signature

(Name of Inspector)

EE
RWD work division
muzaffargarh CCA-1

GENERAL ABSTRACT

Name of Road Bhatulia Devi Mandir to Gangi Chapra

District Muzaffarpur

Block Minapur

Division Muzaffarpur East-2

Length of Road (in Km) 0.900 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)	
1	Jhama metal	14.757	11.737
2	Sand Filling	0.124	
3	Rune Pipe 1000mm dia	1.258	
4	Bamboo Piles	0.000	
	GRAND SUB TOTAL	16.139	13.119
TOTAL COST OF PROJECT IN LACS =		16.139	13.119

Say 13.12 lakh

Ramesh
11/11/2020

JE

RWD

AB
11/11/20

AE

RWD

far
11/11/20

EE

RWD

Technically approved for Rs 13.12 lakh
(Rupees Thirteen lakh twelve thousand only)

Shree
12-12-20
SE

RWD Muzaffarpur
muzaffarpur