

Inspection Report for Flood Damage Work

Date:

1. Name of PIUs - Gyan vibhakar (EE muzaffarpur Galt-1)
2. Name of Block/Road - minapur / siwai Galt p.w. road to kharja Nakara

A. For Road

1. Damage Location/Chainage : 0.121km, 0.220km, 0.800km, 0.990km, 1.3km, 1.8km, 2.5km
2. Damage Length : 281.20 m (0.2812km)
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works : brick bats & local sand
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length : 281.20 m (0.2812km)

B. For Bridge

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works :
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length :

Signature of JE/AE/EE

Free
18.11.20
Signature

(Name of Inspector)

EE
RWD WORK DIVISION
muzaffarpur Galt-1

GENERAL ABSTRACT

Name of Road Siwaipati PWD Road to Khoja Pakari

District Muzaffarpur

Block Minapur

Division Muzaffarpur East-2

Length of Road (in Km) 2.983 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	12.142 11.114
2	Sand Filling	0.237
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	12.380 11.351
TOTAL COST OF PROJECT IN LACS =		12.380

say 11.35 lac.

[Signature]
11/11/2020

JE
RWD

[Signature]
11/11/20

AE
RWD

[Signature]
11/11

EE
RWD

Technically approved for Rs 11.35 lac
(Rupees Eleven lac thirty five thousand only)

[Signature]
12.12.20

SE
RWD work circle
muzaffarpur