

Inspection Report for Flood Damage Work

Date:

1. Name of PIUs - Gyan vibhakar

2. Name of Block/Road - Katha / Dhubuli Bumni Tehara Rd to Sahnauli

A. For Road

1. Damage Location/Chainage : 0.01km, 0.0501km, 0.200km, 0.2951km, 0.300km, 0.5501km, 0.701km
2. Damage Length : 0.178 km (Approx) 0.17775 km
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works : Brick bats
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length : 0.178 km

X B. For Bridge

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works :
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length :

Signature of JE/AE/EE

Spec
21-11-20
Signature

(Name of Inspector)

EE

RWD work Division
Muzaffarpur Ghat-1

GENERAL ABSTRACT

Name of Road Dhubauli Dumri Tehwara Rd to Sahnauli

District Muzaffarpur

Block Katra

Division Muzaffarpur East-2

Length of Road (in Km) 1.074 Km


Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	1.679
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	1.679
TOTAL COST OF PROJECT IN LACS =		1.679

say 1.68 lac




JE

RWD



AE


RWD



EE

RWD

Technically approved for RS 1.68 lac
(Rupees one lac sixty eight thousand only)


26.12.20
SE

RWD WORK circle
muzaffarpur