

Inspection Report for Flood Damage Work

Date:

1. Name of PIUs - Gyan Vibhakar
2. Name of Block/Road - keetha / Bhogwanpur to Agahasi

A. For Road

1. Damage Location/Chainage : 0.01km, 0.0201km, 0.1001km, 0.2501km, 0.3001km, 0.3501km, 0.4001km
2. Damage Length : 0.272 km Approx (0.27186 km)
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works : Brick bats
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length : 0.272 km (0.27186 km)

B. For Bridge

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works :
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length :

Signature of JE/AE/EE

[Signature]
21-11-20
Signature

(Name of Inspector)

EE
RWD work division
Muzaffarabad-1

GENERAL ABSTRACT

Name of Road Bhagwanpur to Agahari

District Muzaffarpur

Block Katra


Division Muzaffarpur East-2


Length of Road (in Km) 0.912 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	3.998
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	3.998
TOTAL COST OF PROJECT IN LACS =		3.998


~~Say 4.00 lac~~
say 3.99 lac


JE
RWD


AE
RWD


EE
RWD

Technically approved for Rs 3.99 lac
(Rupees ~~Three~~ Three lac ninety nine thousand only)


SE
26.12.20

RWD work circle
muzaffarpur