

## Inspection Report for Flood Damage Work

Date

- 1 Name of PIUs- Gyan vibhakar  
2 Name of Block/Road- Katwa / Kharguradih to Dumri pur road take.

A For Road ✓

- 1 Damage Location/Chainage 0.101km, 0.500km, 0.800m, 0.900km, 1.01km, 1.25km, 2.01km  
2 Damage Length 1.32195 km  
3 Nature of Damage  
4 Details of Restoration Works-  
i Material being used in Restoration Works- Brick ball  
ii Equipments/Tools being used in Restoration Works-  
iii Procedure Taken up in Restoration Works-  
iv Restored Length 1.32195 km

B. For Bridge

- 1 Damage Location/Chainage  
2 Damage Length  
3 Nature of Damage  
4 Details of Restoration Works-  
i Material being used in Restoration Works-  
ii Equipments/Tools being used in Restoration Works-  
iii Procedure Taken up in Restoration Works-  
iv Restored Length

Signature of JE/ AE/ EE

EE  
12.12.20

Signature

(Name of Inspector)

EE

RWD work division  
muzaffarpur East - 1



### GENERAL ABSTRACT

Name of Road Khanguradih to Dumri PWD Road Tak

District Muzaffarpur


Block Katra


Division Muzaffarpur East-2

3.430 Km

Length of Road (in Km)		AMOUNT (LAKHS)
Sl. No.	DESCRIPTION	
		27.259
1	Jhama metal	0.000
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	27.259
	GRAND SUB TOTAL	27.259
TOTAL COST OF PROJECT IN LACS =		


say 27.26 lac

  
JE  
RWD

  
AE  
RWD

  
EE  
RWD

Technically approved for RS 27.26 lac  
(Rupees Twenty seven lac twenty six thousand only)

  
SE  
RWD work circle  
muzaffarpur