

Inspection Report for Flood Damage Work

Date:

1. Name of PIUs - Gyan vibhakar

2. Name of Block/Road - Ketha / PWD moter saheb polchow to chandel matarami
asthan

☒ A. For Road

1. Damage Location/Chainage : 0.200km, 0.250km, 0.350km, 0.480km, 0.600km, 0.800km

2. Damage Length : 0.069 Km

3. Nature of Damage :

4. Details of Restoration Works :

i. Material being used in Restoration works : Brick bats

ii. Equipments/Tools being used in Restoration works:

iii. Procedure taken up in Restoration works :

iv. Restored Length : 0.069 Km

☒ B. For Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration Works :


i. Material being used in Restoration works :

ii. Equipments/Tools being used in Restoration works:

iii. Procedure taken up in Restoration works :

iv. Restored Length :

Signature of JE/AE/EE


Signature

(Name of Inspector)

EE

RWD work division muzzaffar

Geeta -1

GENERAL ABSTRACT

Name of Road PWD Master Saheb Pokhar to Changel Maharani Asthan

District Muzaffarpur


Block Katra

Division Muzaffarpur East-2


Length of Road (in Km) 0.900 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	0.537
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	0.537
TOTAL COST OF PROJECT IN LACS =		0.537


say 0.54 lac



JE
RWD




AE
RWD



EE
RWD

Technically approved for Rs 0.54 lac
(Rupees Fifty four thousand only)



SE

RWD WORK CIRCLE
MUZAFFARPUR