

Inspection Report for Flood Damage Work

Date:

1. Name of PIUs - Gyan vibhakar

2. Name of Block/Road - mirzapur / chalo chakra mangi chakra to
Bhersthalia manger Rama house

A. For Road

1. Damage Location/Chainage : 0.20km, 0.50km, 0.60km, 0.70km, 0.80km, 0.90km
2. Damage Length : 360m (0.360km) approx
3. Nature of Damage : Actual - 0.3545 km
4. Details of Restoration Works :
 - i. Material being used in Restoration works : Brick built & local sand
 - ii. Equipments/Tools being used in Restoration works :
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length : 0.360km (0.3545 km)

B. For Bridge

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works :
 - ii. Equipments/Tools being used in Restoration works :
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length :

Signature of JE/AE/EE

Signature

(Name of Inspector)

EE

RWD Home Division
Mirzapur East-1

GENERAL ABSTRACT

Name of Road Chako Chapra Gangi Ctapra to Bhartualia Manger Rana House

District Muzaffarpur

Block Minapur

Division Muzaffarpur East-2

Length of Road (in Km) 0.956 Km

SI. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	2.965
2	Sand Filling	0.265
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	3.229
TOTAL COST OF PROJECT IN LACS =		3.229

say 3.23 lac

[Signature]
13/12/2020
JE
RWD

[Signature]
13/12/20
AE
RWD

[Signature]
13/12/20
EE
RWD

Technically approved for Rs 3.23 lac
(Rupees Three lac Twenty three thousand only)

[Signature]
13/12/20
SE
RWD work circle
muzaffarpur