

Inspection Report for Flood Damage Work

Date

- 1 Name of PIUs- *Gyan vibhakti*
- 2 Name of Block/Road- *Katwa / To 3 pindauli to Budhwaroa road tak.*

A For Road

- 1 Damage Location/Chainage *0.050 km, 0.500 km, 0.900 km, 1.20 km, 1.41 km, 2.00 km, 2.51 km*
- 2 Damage Length - *2.578 km (2.5775 km) approx*
- 3 Nature of Damage
- 4 Details of Restoration Works-
 - i Material being used in Restoration Works- *brick bats*
 - ii Equipments/Tools being used in Restoration Works-
 - iii Procedure Taken up in Restoration Works-
 - iv Restored Length *2.578 km (2.5775 km)*

X B. For Bridge

- 1 Damage Location/Chainage
- 2 Damage Length
- 3 Nature of Damage
- 4 Details of Restoration Works-
 - i Material being used in Restoration Works-
 - ii Equipments/Tools being used in Restoration Works-
 - iii Procedure Taken up in Restoration Works-
 - iv Restored Length

Signature of JE/ AE/ EE

[Signature]
12.12.20
Signature

(Name of Inspector)

EE

*RMD & work division
muzadpur Ghat-1*

GENERAL ABSTRACT

Name of Road T03 Pindeoli to Budhkara Tak

District Muzaffarpur

Block Katra

Division Muzaffarpur East-2

Length of Road (in Km) 3.850 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	41.737
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	41.737
TOTAL COST OF PROJECT IN LACS =		41.737

say 41.74 lac

[Signature]
JE
RWD

[Signature] 25/11/2020
AE
RWD

[Signature]
EE
RWD

Technically approved for Rs 41.74 lac
(Rupees Forty one lac seventy four thousand only)

[Signature]
26/12/20
SE
RWD WORK circle
muzaffarpur